



Category <b>T</b>	<b>Repair Guidance</b>	Ref. No. MME/R004/13C	Page 1 of 1
Coverage <input type="checkbox"/> Distributor only <input checked="" type="checkbox"/> Please inform your dealers		Date Issued November 28, 2013	
Please convey this information to your <input type="checkbox"/> Director <input checked="" type="checkbox"/> General Manager <input checked="" type="checkbox"/> Warranty Dept. <input checked="" type="checkbox"/> Parts Dept. <input checked="" type="checkbox"/> Training Dept. <input checked="" type="checkbox"/> Field Rep.		Date Revised <b>September 02, 2016</b>	
Applicable Models  All models with MZD Connect (Except Mazda3 (BN) and Mazda6 (GL) and/or software Ver.59.00.XXX)		Applicable Countries or Specifications  Europe	

**REVISED****Revision Note: "Applicable Models" and "Description" has been revised.****Subject: PDI action for software update for MZD connect****DESCRIPTION**

In order to deliver new vehicle to the customer in perfect condition, the following action is required to conduct as a part of PDI (Pre Delivery Inspection) at the dealer from now on.

- Check software version and update if it is not the latest one for

- All Models with MZD Connect (CMU (Connectivity Master Unit)) [Except for models with software Ver.59.00.XXX installed]

**BACKGROUND**

Software development is a continuous process in order to further improve the various systems and their operation. Therefore the software which is available at the time of PDI might be more actual than the software which was installed earlier during vehicle production.

**PROCEDURE**

Check the latest available software by referring to the Technical Download Server.  
Check the software level of the vehicle, and if

1. Vehicle's software is latest level → no need to take action
2. Vehicle's software is older → perform software update according to following procedure

For MZD Connect, please refer to SI R115/13.

Naoki Shiozawa  
Manager, Technical Product Support  
Customer Service Division  
Mazda Motor Europe GmbH